

Bell Restoration Work Completed by July 2010



The old ringing room ceiling and bell chamber floor have been removed.

The work was done mainly by Huntingdonshire Bell Restoration Society.



Typical of the timber removed from the old floor and ceiling.



The Eight Sims are located on the new floor below the main bell frame.

The Sim installation has been carried out by our Brampton ringers.



A new floor and ceiling have been installed by Brampton General Builders.

This is about four feet lower in the tower than the previous floor.

Here you can see the Sim ropes together with the Tower Bell ropes.



The next phase of work is to strengthen the old bell frame in this area. We will probably re-hang the third bell on new headstock and bearings, retaining the bell wheel and other fittings.